



Provision of Safety

Visitors to the Lavender facilities are required to act in a responsible manner and report any concerns to the course tutor without delay.

The following notes are for your guidance and assistance during your stay in this centre.

- 1.0 Smoking is not allowed anywhere inside the building. Please use the designated smoking area outside the building and ensure that cigarettes are extinguished and deposited in the receptacle provided.
- 2.0 A building evacuation plan is posted on the wall of each room next to the door. Please make yourself familiar with the Fire Procedures.
- 3.0 Ultrasonic testing courses use various coupling substances which are primarily water based inert material with minimal hazard content. Should any spillage or accident occur, you must inform a member of staff who will deal with it appropriately.
- 4.0 If a first aid is needed for whatever reasons make this known immediately to the tutor.
- 5.0 Many items used in NDT are heavy and dangerous if allowed to fall. Please clean off all couplant residues before lifting metal samples. Couplant can make samples slippery causing a potential hazard during lifting and moving.
- 6.0 Ultrasonic welded plates and pipes weigh up to 25kg. Do not attempt to lift larger samples that are labelled DO NOT LIFT.
- 7.0 Safety shoes are mandatory when doing practical work and shall be worn at all times during the practical sessions of the course. Please make sure you provide your own appropriate safety footwear.
- 8.0 Under no circumstance shall any naked flame be permitted inside the building.
- 9.0 Any evidence of an inability to act in a safe and responsible manner for any reason (including alcohol or drugs) will result in immediate dismissal from the premises.

CONTACT YOUR COURSE TUTOR IF YOU REQUIRE ANY FURTHER INFORMATION.

I have read and understand the above information

Signed: **Dated:**

Name: **Company:**