UK Course Schedule 2020



Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.

Penetrant Testing (PT) Level 1 & 2	Magnetic Testing (MT) Level 1 & 2
13 – 17 July 2 – 6 November 20 – 24 July 23 – 27 November 27 – 31 July 7 – 11 December 3 – 7 August 10 – 14 August 17 – 21 August 24 – 28 August 7 – 11 September 28 Sept – 2 October 12 – 16 October	20 – 24 July 27 – 31 July 10 – 14 August 31 August – 4 Sept 14 – 18 Sept 5 – 10 October 26 – 30 October 9 – 13 November 30 Nov – 4 December
Visual Testing (VT) Level 1 & 2	Basic Radiation Safety (BRS)
17 – 21 August 21 – 25 September 19 – 23 October 16 – 20 November 14 – 18 December	11 & 12 June 16 & 17 July 6 & 7 August 31 August & 1 September
Radiation Protection Supervisor (RPS)	Radiographic Testing (RT) Welds or Castings Level 1 & 2 including BRS
6 – 8 July 2 – 4 September Please note candidates must hold BRS for 9 months to be eligible for RPS	13 – 31 July 3 – 21 August 14 September – 2 October 5 – 23 October 26 October – 13 November 16 November – 4 December 30 November – 18 December
Radiographic Interpretation (RI) Welds or Castings Level 1 & 2	Weld Inspector Level 2
13 – 21 July 3 – 11 August 14 - 22 September 5 – 13 October 26 October – 3 November 16 – 24 November	29 June – 6 July 7 – 14 September Please contact us for Level 1 Weld Inspector course dates
30 November – 8 December Accelerated World	

PT, MT, VT, UT, ET, RT

We offer PCN approved accelerated work experience that counts towards 50% of your total requirement needed for your qualification

UK Course Schedule 2020



TOFD Level 2	Ultrasonic Testing Plate Tester Level 2
21 September – 2 October 7 – 18 December	22 – 26 June 17 – 21 August 12 – 16 October 7 – 11 December
Ultrasonic Inspection Initial Courses (UT) Level 2	Phased Array UT (PAUT) Level 2
Start dates for UT courses: 29 June 13 July 27 July 10 August 24 August 7 September 21 September	13 – 30 July 5 – 22 October 16 November – 3 December If other dates are required, we will try to accommodate them please contact: enquiries@lavender-ndt.com
Level 3 Courses Level 3	High Temperature Hydrogen Attack Detection (HTHA)
TOFD: 6 - 10 July 10 - 14 August (Basic, MT, PT, RTW & UTW) 17 - 21 August (Basic, MT, PT, RTW & UTW) 24 - 28 August (Basic, MT, PT, RTW & UTW) 7 - 11 September (Basic, MT, PT, RTW & UTW) 14 - 18 September (Basic, MT, PT, RTW & UTW) 21 - 25 September (Basic, MT, PT, RTW & UTW) 26 - 30 October (Basic, MT, PT, RTW & UTW) 2 - 6 November (Basic, MT, PT, RT & UT) 7 - 11 December (Basic, MT, PT, RT & UT) 14 - 18 December (Basic, MT, PT, RT & UT) Phased Array Level 3: 7 - 11 September	21 – 25 September
Eddy Current Testing Welds, Forgings or Tubes Level 2	Alternating Current Field Measurement (ACFM) Level 1 & Level 2
6 – 17 July 24 August – 4 September 5 – 16 October 16 – 27 November 23 – 4 December 7 – 18 December	Please contact us for dates enquiries@lavender-ndt.com

Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: enquiries@lavender-ndt.com