

Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. **Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.**

Penetrant Testing (PT) Level 1 & 2	Magnetic Testing (MT) Level 1 & 2
17 – 21 February 24 – 28 February 16 – 20 March 30 March – 3 April 13 – 17 April 27 April – 1 May	10 – 14 February 17 – 21 February 24 – 28 February 2 - 6 March 9 – 13 March 16 – 20 March 23 – 27 March 6 – 10 April 20 – 24 April
Visual Testing (VT) Level 1 & 2	Basic Radiation Safety (BRS)
17 – 21 February 9 – 13 March	9 & 10 January 24 & 25 February 6 & 7 February 20 & 21 February
Radiation Protection Supervisor (RPS)	Radiographic Testing (RT) Welds or Castings Level 1 & 2 including BRS
29 – 31 January 26 – 28 February Please note candidates must hold BRS for 9 months to be eligible for RPS	6 – 24 January 20 January – 7 February 3 – 21 February 17 February – 6 March 2 – 20 March 16 March – 3 April
Radiographic Interpretation (RI) Welds or Castings Level 1 & 2	Weld Inspector Level 2
6 – 14 January 20 – 28 January 3 – 11 February 17 - 25 February 2 – 10 March 16 – 24 March 30 March – 7 April	Please contact us for Level 1 and 2 Weld Inspector course dates

UK Course Schedule 2020



Computed Radiographic Testing Level 2	Ultrasonic Testing Plate Tester Level 2
Please contact us for Level 2 Computed Radiographic Testing dates	27 – 31 January 24 – 28 February 23 – 27 March
Ultrasonic Inspection Initial Courses (UT) Level 2	Phased Array UT (PAUT) Level 2
Start dates for UT courses: 6 th January 20 th January 3 rd February 17 th February 2 nd March 16 th March 30 th March 27 th April	The equipment that will be used for the training will be either the Olympus Omniscan or the M2M Gekko. 6- 23 January 17 February – 5 March 4 – 21 May
Time of Flight Diffraction (TOFD) Level 2	High Temperature Hydrogen Attack Detection (HTHA)
27 January – 7 February 9 – 20 March 20 April – 1 may	10 – 14 February
Eddy Current Testing Welds, Forgings or Tubes Level 2	Alternating Current Field Measurement (ACFM) Level 1 & Level 2
2 – 13 March (welds and forgings) Please enquire for ET Tubes dates	23 – 27 March (Level 1) 30 March – 3 April (Level 2) 23 March – 3 April (Direct entry to Level 2)

Level 3 Courses

Course dates	Training in Basic, MT, PT, UT, VT, RT, ET, PA & TOFD
27 – 31 January	Basic, UT, MT, PT, VT, RT or ETW
17 – 21 February	Basic, UT, MT, PT, VT, RT or ETW
24 – 28 February	Basic, UT, MT, PT, VT, RT or ETW/ETF
9 – 13 March	Basic, UT, MT, PT, VT, RT or ETW/ETW
16 – 20 March	Basic, UT, MT, PT, VT, RT or PA
30 March – 3 April	Basic, UT, MT, PT, VT, RT or ETW
6 – 10 April	Basic, UT, MT, PT & ETW

Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: enquiries@lavender-ndt.com