

Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. **Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.**

Penetrant Testing (PT) Level 1 & 2	Magnetic Testing (MT) Level 1 & 2
13 – 17 April 27 April – 1 May 4 – 8 May 11 – 15 May 18 – 22 May 25 – 29 May	8 – 12 June 15 – 19 June 22 – 26 June 29 June – 3 July
	10 -14 February 24 – 28 February 2 - 6 March 9 – 13 March 16 – 20 March 30 March – 3 April 6 – 10 April 13 – 17 April 27 April – 1 May
Visual Testing (VT) Level 1 & 2	Basic Radiation Safety (BRS)
9 – 13 March 20 – 24 April 1 – 5 June	23 & 24 January 19 – 20 March 2 – 3 April
Radiation Protection Supervisor (RPS)	Radiographic Testing (RT) Welds or Castings Level 1 & 2 including BRS
29 – 31 January 26 – 28 February Please note candidates must hold BRS for 9 months to be eligible for RPS	20 January – 7 February 16 March – 3 April 30 March - 17 April 27 April - 15 May 11 – 29 May
Radiographic Interpretation (RI) Welds or Castings Level 1 & 2	Weld Inspector Level 2
20 – 28 January 3 – 11 February 17 - 23 February 16 – 24 March 30 March – 7 April 27 April – 5 May	Please contact us for Level 1 and 2 Weld Inspector course dates

UK Course Schedule 2020



Computed Radiographic Testing Level 2	Ultrasonic Testing Plate Tester Level 2
Please contact us for Level 2 Computed Radiographic Testing dates	27 – 31 January 24 – 28 February 23 – 27 March
Ultrasonic Inspection Initial Courses (UT) Level 2	Phased Array UT (PAUT) Level 2
Start dates for UT courses: 20 th January 17 th February 2 nd March 16 th March 30 th March 27 th April	The equipment that will be used for the training will be either the Olympus Omniscan or the M2M Gekko. 17 February – 5 March 4 – 21 May
Time of Flight Diffraction (TOFD) Level 2	High Temperature Hydrogen Attack Detection (HTHA)
27 January – 7 February 9 – 20 March 20 April – 1 may	23 – 27 March
Eddy Current Testing Welds, Forgings or Tubes Level 2	Alternating Current Field Measurement (ACFM) Level 1 & Level 2
10 – 21 February (Welds only) - Full 2 – 13 March (Welds or forgings) - Full Please enquire for ET Tubes dates	23 – 27 March (Level 1) 30 March – 3 April (Level 2) 23 March – 3 April (Direct entry to Level 2)

Level 3 Courses

Course dates	Training in Basic, MT, PT, UT, VT, RT, ET, PA & TOFD
27 – 31 January	Basic, UT, MT, PT, VT, RT or ETW
9 – 13 March	Basic, UT, MT, PT, VT, RT or ETW
16 – 20 March	Basic, UT, MT, PT, VT, RT or PA
30 March – 3 April	Basic, UT, MT, PT, VT, RT or ETW
6 – 10 April	Basic, UT, MT, PT & ETW
20 – 24 April	Basic, UT, MT, PT, VT, RT & ETW
4 – 8 May	Basic, UT, MT, PT, VT, RT & ETW
11 – 15 May	Basic, MT, PT & ETW
18 – 22 May	Basic, UT, MT, PT, VT, RT or ETW
15 – 19 June	Basic, UT, MT, PT, VT, RT, ETW or TOFD
22 – 26 June	Basic, UT, MT, PT, VT, RT or ETW

Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: enquiries@lavender-ndt.com