

Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. **Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.**

Penetrant Testing (PT) Level 1 & 2		Magnetic Testing (MT) Level 1 & 2	
3 – 7 February	8 – 12 June	10 -14 February	6 – 10 April
13 – 17 April	15 – 19 June	24 – 28 February	13 – 17 April
27 April – 1 May	22 – 26 June	2 - 6 March	27 April – 1 May
4 – 8 May	29 June – 3 July	9 – 13 March	
11 – 15 May		30 March – 3 April	
18 – 22 May			
25 – 29 May			
Visual Testing (VT) Level 1 & 2		Basic Radiation Safety (BRS)	
9 – 13 March		2 -3 March	
20 – 24 April		2 – 3 April	
1 – 5 June			
Radiation Protection Supervisor (RPS)		Radiographic Testing (RT) Welds or Castings Level 1 & 2 including BRS	
Please note candidates must hold BRS for 9 months to be eligible for RPS		16 March – 3 April	
		30 March - 17 April	
		27 April - 15 May	
		11 – 29 May	
Radiographic Interpretation (RI) Welds or Castings Level 1 & 2		Weld Inspector Level 2	
3 – 11 February		Please contact us for Level 1 and 2 Weld Inspector course dates	
17 - 23 February			
16 – 24 March			
30 March – 7 April			
27 April – 5 May			

UK Course Schedule 2020



Computed Radiographic Testing Level 2	Ultrasonic Testing Plate Tester Level 2
Please contact us for Level 2 Computed Radiographic Testing dates	24 – 28 February 23 – 27 March 6 – 10 April 4 – 8 May 1 – 5 June
Ultrasonic Inspection Initial Courses (UT) Level 2	Phased Array UT (PAUT) Level 2
Start dates for UT courses: 17 th February 2 nd March 16 th March	30 th March 27 th April 25 th May 8 th June
	The equipment that will be used for the training will be either the Olympus Omniscan or the M2M Gekko. 17 February – 5 March 4 – 21 May
Time of Flight Diffraction (TOFD) Level 2	High Temperature Hydrogen Attack Detection (HTHA)
9 – 20 March 20 April – 1 May	23 – 27 March
Eddy Current Testing Welds, Forgings or Tubes Level 2	Alternating Current Field Measurement (ACFM) Level 1 & Level 2
10 – 21 February (Welds only) - Full 2 – 13 March (Welds or forgings) - Full Please enquire for ET Tubes dates	23 – 27 March (Level 1) 30 March – 3 April (Level 2) 23 March – 3 April (Direct entry to Level 2)

Level 3 Courses

Course dates	Training in Basic, MT, PT, UT, VT, RT, ET, PA & TOFD
27 – 31 January	Basic, UT, MT, PT, VT, RT or ETW
9 – 13 March	Basic, UT, MT, PT, VT, RT or ETW
16 – 20 March	Basic, UT, MT, PT, VT, RT or PA
30 March – 3 April	Basic, UT, MT, PT, VT, RT or ETW
6 – 10 April	Basic, UT, MT, PT & ETW
20 – 24 April	Basic, UT, MT, PT, VT, RT & ETW
4 – 8 May	Basic, UT, MT, PT, VT, RT & ETW
11 – 15 May	Basic, MT, PT & ETW
18 – 22 May	Basic, UT, MT, PT, VT, RT or ETW
15 – 19 June	Basic, UT, MT, PT, VT, RT, ETW or TOFD
22 – 26 June	Basic, UT, MT, PT, VT, RT or ETW

Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: enquiries@lavender-ndt.com