

Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. **Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.**

Penetrant Testing (PT) Level 1 & 2		Magnetic Testing (MT) Level 1 & 2	
13 – 17 April 27 April – 1 May 4 – 8 May 11 – 15 May 18 – 22 May 25 – 29 May	8 – 12 June 15 – 19 June 22 – 26 June 29 June – 3 July	10 -14 February 24 – 28 February 2 - 6 March 9 – 13 March 30 March – 3 April	6 – 10 April 13 – 17 April 27 April – 1 May
Visual Testing (VT) Level 1 & 2		Basic Radiation Safety (BRS)	
9 – 13 March 20 – 24 April 1 – 5 June		2 -3 March 2 – 3 April	
Radiation Protection Supervisor (RPS)		Radiographic Testing (RT) Welds or Castings Level 1 & 2 including BRS	
Please note candidates must hold BRS for 9 months to be eligible for RPS		16 March – 3 April 30 March - 17 April 27 April - 15 May 11 – 29 May	
Radiographic Interpretation (RI) Welds or Castings Level 1 & 2		Weld Inspector Level 2	
17 - 23 February 16 – 24 March 30 March – 7 April 27 April – 5 May		Please contact us for Level 1 and 2 Weld Inspector course dates	

UK Course Schedule 2020



Computed Radiographic Testing Level 2	Ultrasonic Testing Plate Tester Level 2
Please contact us for Level 2 Computed Radiographic Testing dates	24 – 28 February 23 – 27 March 6 – 10 April 4 – 8 May 1 – 5 June
Ultrasonic Inspection Initial Courses (UT) Level 2	Phased Array UT (PAUT) Level 2
Start dates for UT courses: 17 th February 30 th March 2 nd March 27 th April 16 th March 25 th May 8 th June	The equipment that will be used for the training will be either the Olympus Omniscan or the M2M Gekko. 17 February – 5 March 4 – 21 May
Time of Flight Diffraction (TOFD) Level 2	High Temperature Hydrogen Attack Detection (HTHA)
9 – 20 March 20 April – 1 May	23 – 27 March
Eddy Current Testing Welds, Forgings or Tubes Level 2	Alternating Current Field Measurement (ACFM) Level 1 & Level 2
10 – 21 February (Welds only) 13 – 24 April (Welds or forgings) Please enquire for ET Tubes dates	23 – 27 March (Level 1) 30 March – 3 April (Level 2) 23 March – 3 April (Direct entry to Level 2)

Level 3 Courses

Course dates	Training in Basic, MT, PT, UT, VT, RT, ET, PA & TOFD
16 – 20 March	PA only
30 March – 3 April	Basic, UT, MT, PT, VT, RT or ETW
6 – 10 April	Basic, MT, PT & ETW
20 – 24 April	Basic, UT, MT, PT, VT, RT & ETW
4 – 8 May	Basic, UT, MT, PT, VT, RT & ETW
11 – 15 May	Basic, MT, PT & ETW
18 – 22 May	Basic, UT, MT, PT, VT, RT or ETW
15 – 19 June	Basic, UT, MT, PT, VT, RT, ETW or TOFD
22 – 26 June	Basic, UT, MT, PT, VT, RT or ETW

Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: enquiries@lavender-ndt.com