

## Level 1 & 2 Courses

Lavender International offers more than 300 NDT courses each year worldwide in accordance with internationally recognised and employer-based certification schemes such as PCN (BS EN ISO 9712), EN4179, NAS 410 and SNT-TC-1A. **Please note the availability of our courses may be subject to change daily, please contact us to confirm if the course is still available.**

<b>Penetrant Testing (PT)</b> Level 1 & 2	<b>Magnetic Testing (MT)</b> Level 1 & 2
13 – 17 April 27 April – 1 May 4 – 8 May 11 – 15 May 18 – 22 May 25 – 29 May	8 – 12 June 15 – 19 June 22 – 26 June 29 June – 3 July
10 -14 February 24 – 28 February 2 - 6 March 9 – 13 March 30 March – 3 April	6 – 10 April 13 – 17 April 27 April – 1 May
<b>Visual Testing (VT)</b> Level 1 & 2	<b>Basic Radiation Safety (BRS)</b>
9 – 13 March 20 – 24 April 1 – 5 June	2 -3 March 2 – 3 April
<b>Radiation Protection Supervisor (RPS)</b>	<b>Radiographic Testing (RT)</b> Welds or Castings Level 1 & 2 including BRS
<b>Please note candidates must hold BRS for 9 months to be eligible for RPS</b>	16 March – 3 April 30 March - 17 April 27 April - 15 May 11 – 29 May
<b>Radiographic Interpretation (RI)</b> Welds or Castings Level 1 & 2	<b>Weld Inspector</b> Level 2
17 - 23 February 16 – 24 March 30 March – 7 April 27 April – 5 May	Please contact us for Level 1 and 2 Weld Inspector course dates

# UK Course Schedule 2020



<b>Computed Radiographic Testing</b> Level 2	<b>Ultrasonic Testing Plate Tester</b> Level 2
Please contact us for Level 2 Computed Radiographic Testing dates	24 – 28 February 23 – 27 March 6 – 10 April 4 – 8 May 1 – 5 June
<b>Ultrasonic Inspection Initial Courses (UT)</b> Level 2	<b>Phased Array UT (PAUT)</b> Level 2
Start dates for UT courses: 17 <sup>th</sup> February      30 <sup>th</sup> March 2 <sup>nd</sup> March            27 <sup>th</sup> April 16 <sup>th</sup> March           25 <sup>th</sup> May 8 <sup>th</sup> June	The equipment that will be used for the training will be either the Olympus Omniscan or the M2M Gekko.  17 February – 5 March 4 – 21 May
<b>Time of Flight Diffraction (TOFD)</b> Level 2	<b>High Temperature Hydrogen Attack Detection (HTHA)</b>
9 – 20 March 20 April – 1 May	23 – 27 March
<b>Eddy Current Testing</b> Welds, Forgings or Tubes Level 2	<b>Alternating Current Field Measurement (ACFM)</b> Level 1 & Level 2
10 – 21 February (Welds only) 2 – 13 March (welds only) 13 – 24 April (Welds or forgings)  <b>Please enquire for ET Tubes dates</b>	23 – 27 March (Level 1) 30 March – 3 April (Level 2) 23 March – 3 April (Direct entry to Level 2)

## Level 3 Courses

<b>Course dates</b>	<b>Training in Basic, MT, PT, UT, VT, RT, ET, PA &amp; TOFD</b>
16 – 20 March	PA only
30 March – 3 April	Basic, UT, MT, PT, VT, RT or ETW
6 – 10 April	Basic, MT, PT & ETW
20 – 24 April	Basic, UT, MT, PT, VT, RT & ETW
4 – 8 May	Basic, UT, MT, PT, VT, RT & ETW
11 – 15 May	Basic, MT, PT & ETW
18 – 22 May	Basic, UT, MT, PT, VT, RT or ETW
15 – 19 June	Basic, UT, MT, PT, VT, RT, ETW or TOFD
22 – 26 June	Basic, UT, MT, PT, VT, RT or ETW

## Recertification Examinations

We run recertification examinations every week in the majority of our methods. Please contact us for more details: [enquiries@lavender-ndt.com](mailto:enquiries@lavender-ndt.com)